

## Instabilities on the Booster Front Porch

E. Gill

February 1989

Collider Accelerator Department  
**Brookhaven National Laboratory**

**U.S. Department of Energy**

USDOE Office of Science (SC)

Notice: This technical note has been authored by employees of Brookhaven Science Associates, LLC under Contract No. DE-AC02-76CH00016 with the U.S. Department of Energy. The publisher by accepting the technical note for publication acknowledges that the United States Government retains a non-exclusive, paid-up, irrevocable, world-wide license to publish or reproduce the published form of this technical note, or allow others to do so, for United States Government purposes.

## **DISCLAIMER**

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Number 249AGS Studies Report

Date(s) February 15, 1989 Time(s) 1200 - 1600  
Experimenter(s) E. Gill, E. Raka, J.M. Brennan  
Reported by E. Raka, L. Ahrens  
Subject Instabilities on the Booster Front Porch



As part of the VHF cavity study of February 15, 1989, the high intensity characteristics of the beam without  $268 f_0$  excitation (VHF cavity off) were investigated. It was first noted that at intensity approaching  $10^{13}$  protons (total in 12 bunches) there was a strong transverse vertical instability present. This was suppressed by lowering the vertical tune on the 1.5 GeV flattop ( $GC \approx 4900$ ) while maintaining the "normal" damper settings. Next, we found that the beam became significantly debunched before the end of the 200 msec flattop was reached (at  $\approx 10^{13}$ ). As the intensity was increased to approximately  $1.2 \times 10^{13}$ , the blowup began 50-60 msec from the start of the flattop and some beam loss ensued. One could see unequal bunch population at the end of the flattop and significant bunch shape distortion and elongation.

At lower intensity, approximately  $6 \times 10^{12}$ , the instability was not present. Also, at intermediate intensity when there was blowup but no loss, the beam went through transition with no loss. Using a mountain-range display, it was possible to make a tentative identification of the coupled bunch mode present during the early part of the growth. It is either an  $n = 1$  or  $n = 11$  mode. This was also verified by using the spectrum analyzer (J.M. Brennan) to measure the amplitude of the 11th harmonic of the beam current relative to the 12th or rf component with and without the instability present. For the former, there was less than 10 db difference while at lower intensity the difference was  $> 30$  db. We note that the rf frequency was 4.171 MHz on the flattop.

This study marked the first time intensities above  $10^{13}$  have been accelerated across what will be the Booster injection porch. Understanding and controlling instabilities on this porch at these and higher intensities is clearly essential--a high priority effort.

The figure below shows the mountain range with the instability present (bunch intensity vs. time looking at the same bunches at 25  $\mu$ s intervals during the porch). One presumably trivial but as yet unexplained problem is that the synchrotron frequency derived from this picture (1.2 kHz) is too small (2 kHz calculated from reasonable rf parameters).

The first step in a study program to clarify the longitudinal blowup could involve observing the dependence of this phenomenon on frequency (vary the energy of the porch).



F-20 wall monitor "mountain range" photo and sketch; 25  $\mu$ s delay between sweeps, sweep speed adjusted to show 4+ bunches (100 ns/cm), 2 ms total time for display.