

2 Attempt to Extract Beam from H10

G. Bagley

April 1973

Collider Accelerator Department
Brookhaven National Laboratory

U.S. Department of Energy

USDOE Office of Science (SC)

Notice: This technical note has been authored by employees of Brookhaven Science Associates, LLC under Contract No.AT(30-1)-16 with the U.S. Department of Energy. The publisher by accepting the technical note for publication acknowledges that the United States Government retains a non-exclusive, paid-up, irrevocable, world-wide license to publish or reproduce the published form of this technical note, or allow others to do so, for United States Government purposes.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

NO. 12

COMMISSIONING
FEB STUDIES

Blumberg
FRIDAY, APRIL 20, 1973
0600 - 1400

G. Bagley, G. Bennett, L. Blumberg, A. Soukas, E. Kaha

OBJECTIVE: 2ND ATTEMPT TO EXTRACT BEAM.

(1). ACTUAL BEAM TIME: 1230 → 1420 WITH MANY INTERRUPTIONS FROM LINAC. ABOUT $\frac{1}{2}$ HOUR OF GOOD TIME. ALL COMPONENTS CAME ON AT NOMINAL OPERATING VALUES AND PULSED SATISFACTORILY. NOTED A RANDOM JUMP OF 6 nSEC IN TIMING OF CIS BEAM KICKER WHICH APPEARED TO EFFECT OTHER POWER SUPPLIES IN E10 HOUSE: E10 BUNCHER BUMP SUPPLY OCCASIONALLY KICKED OFF, E10 MAGNET SUPPLY MULTI-TRIGGERED. COULD NOT DETERMINE CAUSE.

(2). CIS KICKER CAUSED CURRENT OVERLOADS AND SUBSEQUENT TRIP-OFF OF CD RF STATION. PULSE ON RADIAL ERROR SIGNAL ALSO NOTED CONCURRENT WITH KICKER PULSE. WE CLAMPED RADIAL LOOP DURING THIS INTERVAL BUT LARGE TRANSIENT STILL OBSERVED FROM CD STATION. REDUCED CF AMPLITUDE $\sim 20\%$ TO AVOID TRIPPING OFF STATION. PROBABLE CAUSE IS DIRECT PICK-UP OF CIS SIGNAL IN CD AMPLIFIER OR CAVITY. REQUIRES MORE STUDY SINCE WE PLAN MUCH LARGER (5000 A → 20 000 A) PEAK CURRENTS IN BEMY KICKERS FOR FULL EXTRACTION OF ABS BEAM.

(3) INTERMITTENT TIMING PROBLEM PREVENTED EXTRACTION.