

# DETERIORATION OF ELECTRICAL INSULATION OF MAIN MAGNET COILS FROM MAGNET G-1

E. J. Rutan

November 1969

Collider Accelerator Department  
**Brookhaven National Laboratory**

**U.S. Department of Energy**

USDOE Office of Science (SC)

Notice: This technical note has been authored by employees of Brookhaven Science Associates, LLC under Contract No.AT-30-2-GEN-16 with the U.S. Department of Energy. The publisher by accepting the technical note for publication acknowledges that the United States Government retains a non-exclusive, paid-up, irrevocable, world-wide license to publish or reproduce the published form of this technical note, or allow others to do so, for United States Government purposes.

## **DISCLAIMER**

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Accelerator Department  
BROOKHAVEN NATIONAL LABORATORY  
Associated Universities, Inc.  
Upton, N.Y.

AGS DIVISION TECHNICAL NOTE

No. 70

E.J. Rutan

DETERIORATION OF ELECTRICAL INSULATION  
OF MAIN MAGNET COILS FROM MAGNET G-1

During a routine inspection of the coils on magnet G-1, some burning was noticed on the micarta insulating spacers at the up-stream bracket. The coils were removed. The burned spots were at areas at the edges of the micarta spacers under end brackets and one side bracket, (third from the up-stream end about the middle of the coil side).

The coils on magnet G-1 are of the original National Coil Company production, mica tape with polyester impregnant. This magnet was in a low radiation area until 1962. Since then, it has been exposed to the radiation from the two targets at F-20.

A sketch of the coil assembly on the magnet is shown in Fig. 1. Photographs of the burned areas are shown in Figs. 2, 3, 4, 5, 6 and 7. (The coil numbers are shown on Fig. 1.)

The mica coil insulation at the burned areas was not punctured. Coil 372 at the burned area (using a 1-3/4 in. diameter electrode) withstood 6 kV ac for 15 seconds. Coil 349 at the burned area had too great a leakage current at 6 kV but withstood 3 kV for 30 seconds.

The micarta insulation had the appearance of being eroded. Coil 349 was positive to ground and coils 372 and 396 were negative to ground.

New coils and micarta insulation had been put on the magnet before the tests reported herein were made. Changes were being made on magnet G-11 which is also in a high radiation area. It was decided, after discussions between Messrs. Czaja, Gefers, Grisoli, Plotkin and Rutan to use two mica plates with a film of Kapton (polyimide) between. The mica selected was NEMA Grade 9 rigid plate with inorganic bond. This provides the high resistance of mica to radiation and ionization (corona). The Kapton film has high radiation resistance and has a high fire resistance. This is a trial installation.

This new combination will be inspected during shutdowns over the next few years.

A number of tests for surface and volume insulation resistance were made on the coils. Tests were also made at high voltage both with dc and ac potentials. These are summarized in a supplementary report for record purposes.

When testing at high voltage, a 1-3/4 in. diameter cylindrical electrode with rounded edges was used. In areas where the surface resistance was lower, a sparking developed which seemed to be under the outer impregnated glass tape of the magnet coils. These sparks would burn an irregular path from the electrode. With the dc tester, due to its limited ampere rating, usually only one path was burned at a time. If it stopped some distance out, a new one would start. These are shown on Figs. 8 and 9. With the ac tester, several paths would burn at the same time. With both sets, the voltage had to be kept below the value which caused trip-out currents to flow.

An attempt will be made to explain the creepage actions in a supplementary report which will also include the test data.

(Note - Color photographs Figs. 2 to 9 are included only with the original copy available at the Accelerator Department office.)

Distr.  
J. Allinger  
J.G. Cottingham  
M. Czaja  
W. Gefers  
J.J. Grisoli  
Admin. Group

BY EJO DATE 10/69


SUBJECT SCHEMATIC COIL MOUNTING - MAIN MAGNET - MICARTA INSULATION SPACERS

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_


CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_

JOB NO. \_\_\_\_\_


DEPT. OR PROJECT LATION SPACERS




MAGNET G-1 PLAN




ELEVATION AT A-A




ELEVATION AT B-B



ASSEMBLED




DISASSEMBLED



ASSEMBLED WITHOUT METAL PLATE (SEE FIG 2)






DISASSEMBLED

# 596

ACTIVE WITH PHYSICS HANDLING OSAL  
RAI  
HE  
REF

ASSEMBLED



DISASSEMBLED

500 12

COIL-349

COIL-349