

Set up of FEB Power Supply Amplitudes, Timing, Polarity

L. Blumberg

August 1973

Collider Accelerator Department
Brookhaven National Laboratory

U.S. Department of Energy

USDOE Office of Science (SC)

Notice: This technical note has been authored by employees of Brookhaven Science Associates, LLC under Contract No.AT(30-1)-16 with the U.S. Department of Energy. The publisher by accepting the technical note for publication acknowledges that the United States Government retains a non-exclusive, paid-up, irrevocable, world-wide license to publish or reproduce the published form of this technical note, or allow others to do so, for United States Government purposes.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

NO. 32

Blumberg
WEDNESDAY, AUGUST 15, 1973

FEB BEAM COMMISSIONING STUDY

Scheduled 0001-0800

BLUMBERG, KEANE

Actual 0100-0630

WE DEVOTED SHIFT TO SET-UP OF POWER SUPPLY AMPLITUDES AND TIMING AND GENERAL SYSTEM CHECK-OUT. NO EXTRACTION. WE FOUND INCORRECT POLARITY INDICATION ON CURRENT IN H16,17 BACKLEG WINDINGS BY OBSERVING RELATIVE POLARITIES OF B SIGNALS FROM E3,4, E16,17, H3,4 AND H16,17. FURTHER CONFIRMED BY FACT THAT H-SUPERPERIOD ORBIT BUMP KILLS BEAM. REVERSED CABLES FOR THAT BUMP AND CONFIRMED THAT BUMP NOW DOES NOT CAUSE BEAM LOSS. TURNED AGS OVER TO OPERATIONS AT 6:30 FOR VACUUM SCANS AND COOL-DOWN.

BEAM SET-UP IS SERIOUSLY HAMPERED BY HAVING TO USE THE MANUAL DATAON CHASSIS AT MAIN CONTROL CONSOLE. WE NEED COMPUTER AND BUG-FREE "PAGE 8" CODE.