

## Check Discrepancy Between Calculated and Expt. Emittance

J. Claus

April 1973

Collider Accelerator Department  
**Brookhaven National Laboratory**

**U.S. Department of Energy**

USDOE Office of Science (SC)

Notice: This technical note has been authored by employees of Brookhaven Science Associates, LLC under Contract No.AT(30-1)-16 with the U.S. Department of Energy. The publisher by accepting the technical note for publication acknowledges that the United States Government retains a non-exclusive, paid-up, irrevocable, world-wide license to publish or reproduce the published form of this technical note, or allow others to do so, for United States Government purposes.

## **DISCLAIMER**

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

NO. 14

Blumling

Injection Studies

J. Claus

April 25, 1973  
0400 - 0800

Objective:

To trace cause of discrepancy between computed consequences of emittance measurements and experimental evidence.

Procedure:

Measure emittance of 200 MeV beam using PDP-10 program "MENIL", calculate expected beam behavior using PDP-10 program "ORTHO" and compare it with experimental beam profiles obtained by means of SEM scans, using SEM 7, 8 and 11. Additional information is yielded by the currents intercepted by the copper blocs of the aperture restriction at the inflector entrance.

Results:

Measurements were taken as planned. Had some difficulty because it was not realized that emittance measurements and SEM scans are incompatible so that they must be done consecutively rather than simultaneously. Program MENIL may not be on the computer during SEM scans. The discrepancy noted previously (April 17-18) was still present. The indicated emittance had changed drastically since that time, particularly for the vertical plane. Comparing the raw data with the profiles from SEM 7, we concluded that the analogue electronics for the emittance measurement may be sick. It seems to respond non-linearly, beginning to saturate at low signal levels. The copper bloc measurements suggested that the beam is more than 4 cm high and displaced upward with respect to the inflector center line.

Since the machine operated nicely (34 mA during 100  $\mu$ sec on AGS 1 producing a peak circulating beam of  $10^{13}$  and an intensity of  $(4.7 - 5) \times 10^{12}$  just before transition), I spent the rest of the time on another short sample efficiency run. For the first time I obtained a practically triangular efficiency curve while the loss pattern suggested a  $v_H$  very close to 8.6.